

Release Notes for 2.13P4 consisting of ACU SW 3610 and SCU SW 1081

Bugfixes:

- Since the „Unbalanced Load Detection“ was available on the ACU, the „End of Charge“ feature of the local load balancing did not work anymore. This bug is fixed in this firmware.
- After temporary breakdowns of the backend-connection, wrong metervalues were sent in some cases. This bug is fixed in this firmware.