

Release Notes for HCC3 v1.12

Functional changes

- The firmware now supports all WLAN module variants of the AMTRON® series.
- Update of the firmware of the WLAN module SiLabs WGM110 from v1.1.1 to v1.1.7.

Errors and troubleshooting

- Improvement in stability when operating with the WLAN module SiLabs WGM110.
- Improvement in stability when operating with the SMA Sunny Home Manager.
- When operating with the WLAN module SiLabs WGM110, the DHCP server functionality was also active in STA mode.
- When operating with the WLAN module SiLabs WGM110, whitelist entries could not be deleted via the service interface.
- The check for permissible entries in the service interface was improved.
- When operating in SCU mode, short-term connection problems occurred sporadically in larger installations. These were not critical for the charging process; however, they could lead to increased error messages when operating on a backend.