

Release Notes for 2.13P2 consisting of ACU SW 3590 and SCU SW 1081

Improvements:

- Partly missing measurement values or values with incorrect format after temporarily offline operation are correct with this bug fixing.